






SHUNTS



SH-1~150A/50mV STAND





SH-200A/50mV STAND



SH-200A/50mV






SH-250A~600/50mV



A	S	P	W	H	D	L	d	L1	L2
250A	118	86	30	20	$\phi 10$	40	M5	16	24
300A	118	86	35	20	$\phi 12$	40	M5	16	24
400A	118	86	45	20	$\phi 12$	40	M5	16	24
500A	118	86	55	20	$\phi 12$	40	M5	16	24
600A	118	86	55	20	$\phi 12$	40	M5	16	24

SH-800A~1500A/50mV



A	S	P	W	H	D	L	d	L1	L2
800A	118	86	20	35	$\phi 12$	40	M5	16	24
1000A	158	120	30	35	$\phi 12$	40	M5	16	24
1200A	158	120	30	40	$\phi 12$	40	M5	16	24
1500A	158	120	30	50	$\phi 12$	40	M5	16	24